

Appendix : Photographs of damage



Photo 1 Collapse of two story houses (Courtesy: by E.Rodriguez Grandos) (Armenia)



Photo 2 Collapse of two story houses (Courtesy: by E.Rodriguez Grandos) (Armenia)



Photo 3 Collapse of two story houses (Courtesy: by E.Rodriguez Grandos) (Armenia)



Photo 4 Collapse of two story houses with bamboo frame plastered wall (Armenia)



Photo 5 Damage to unreinforced masonry wall (Armenia)



Photo 6 Collapse of two story houses (Armenia)



Photo 7 Collapse of two story houses (Armenia)



Photo 8 Collapse of masonry wall structures (Armenia)



Photo 9 Severe damaged area in Armenia City



Photo 10 Severe damaged area in Armenia City



Photo 11 Fall of masonry walls (Armenia)



Photo 12 Fall of masonry walls (Armenia)



Photo 13 Damage to building on hillside (Armenia)



Photo 14 Damage to irregular building (Armenia)



Photo 15 Damage to first story of building



Photo 16 Slope failure along the road between Calarca and Barcelona



Photo 17 Slope failure along the road between Calarca and Barcelona



Photo 18 Slope failure along the road between Calarca and Barcelona



Photo 19 Slope failure at Armenia City